

Shadow Inspection

Customer: Ron Henry Car: Shadow I
 VIN: LRC16815 Mileage: 34,917

Underhood

	Good	Fair	Bad
Radiator: freezes @ <u>-10°F Full, looks diluted, should change</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Pressure Valve: Vents @ <u>15Lbs.</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Overflow Tank: <u>Ok</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Oil: <u>Clean, about 2 quarts overfilled</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Washer Fluid: <u>1/2 Full, not leaking</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Brake Boils @ <u>RR363, Tank could use cleaning</u> (See Picture #2)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission fluid: <u>Clean, full</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Belts: <u>Good</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Radiator Hoses: <u>Good</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Vacuum Hoses: <u>Old and hard, replaced 2 on air intake valve</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Carburettors: <u>No apparent leaks, choke works</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fuel Hoses: <u>Original</u>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Fuel Filters: <u>Should be taken apart and checked</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ignition Coil: <u>Good</u> Date: _____	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Plug Wires: <u>Ok</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spark Plugs: <u>Look good</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Distributor Cap: <u>Rotor, points all are as new</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Heater Hoses: <u>Old, but ok</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Shadow Inspection pg. 2

Good Fair Bad

Air Filter: Ok

Power steering fluid s/b Dexron: is full and clean

Fan clutch: Ok

Fuses: _____

A/C cowl filters: _____

Compression Cyl: Did not perform test-engine knocking

Under Car

Front Tire Pressure: R-- 34 Date: 18/05 L-- 34 Date: 18/05

Front Tire Tread: R High 9/32 Low 9/32 , L High 9/32 Low 9/32

Front Brake Linings: Ok

Front Brake Hoses: **Old** (See Picture #6)

Discs: Ok

Calipers: Ok

Block weep holes: Ok

Exterior

	Good	Fair	Bad
Windshield Wipers: Very bad (See picture # 3)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Washers: INOP, circuit is ok-pump is bad	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Low Beams: Ok-Halogen replacement type	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
High Beams: Work ok, drivers side has moisture in lens	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Front Turn Signals: Ok-passenger repeater has moisture in it	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Rear Turn Signals: Ok	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Front Side Marker: Ok	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Front Parking Lights: Ok	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Instrument Panel: Speedometer light INOP	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Tail Lights: Ok	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Brake Lights: Ok	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Right Side Marker: Ok	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Reverse Lights: Ok	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
License: Ok	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Interior Lights: INOP	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Hazard Lights: Ok	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn: Ok	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Boot Lamp: INOP	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Glove Box Lamp: INOP	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Fuse Board Lamp: N/A	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Windows: Barely work, right rear is not going up	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Power Door Locks: INOP	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Mechanic Notes

● Engine is mechanically noisy, piston slap on B4

● Leveling solenoid is leaking– see photo album (See Picture # 13)

● Rat trap cover is missing (See Picture # 9)

● Bellows on steering shaft torn (See Picture # 8)

● Rust forming under backlight under vinyl top. (See Picture # 18)

● Speedometer does not work